

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

California Department of Fish and Game Shea Levee

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	0.30	10/21/2016 10/21/2016	Tariq Chechi

LM Start		Rating **	A	Issue No.	7
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_NA0018_01_s_2013_7				
Comment Code					
Inspector Comment					
The LMA has the O&M manuals.					

No Photos

LM Start		Rating **	M	Issue No.	8
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_NA0018_01_s_2012_8				
Comment Code					
Inspector Comment					
The LMA has not completed any training and does not have an available flood plan.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

California Department of Fish and Game Shea Levee

No Photos

View of the levee with no maintenance done.View of the levee with no maintenance done.Page 2 of 4

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	0.30	10/21/2016 10/21/2016	Tariq Chechi

LM Start	0.10	Rating **	M	Issue No.	1
LM End	0.30	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			40.511185 °	40.510670 °
				-122.360553 °	-122.361203 °
DWR ID	DWR_NA0018_01_s_2012_1				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

10/21/2016

LM Start	0.21	Rating **	M	Issue No.	4					
LM End	0.26	Issue Type +	Ma	Location *	WS					
Category	Earthen Levee			GPS Latitude/Longitude						
				Start	End					
Item	Trim / Thin Trees			40.511518 °	40.508234 °					
				-122.360100 °	-122.363430 °					
DWR ID	DWR_NA0018_01_s_2012_4									
Comment Code										
T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.										
Inspector Comment										

LM Start	0.21	Rating **	M	Issue No.	4 (cont)
LM End	0.26	Issue Type +	Ma	Location *	WS

A photograph showing a dirt road or path leading towards a body of water, likely a reservoir or lake. The foreground is dominated by dry, yellowish-brown grass and some low-lying vegetation. The road curves slightly to the left in the distance. On the right side of the road, there are dense green bushes and trees. The water is visible on the right side of the frame, reflecting the sky. The sky is clear and blue. In the bottom right corner, there is a date stamp that reads "09/25/2015".

* Location	** Rating	+ Issue Type
LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

California Department of Fish and Game Shea Levee

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	0.30	10/21/2016 10/21/2016	Tariq Chechi

LM Start	0.22	Rating **	C	Issue No.	6
LM End	0.30	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		40.510671°	40.511185°	
			122.360944°	122.360553°	
DWR ID	DWR_NA0018_01_s_2013_6				
Comment Code					
A2 : Repair the levee slope damaged by livestock and prevent large animal access.					
Inspector Comment					
The livestock damaged the L/S slope.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---